

MULTIMETER



Description :

- Maintenance multimeter. • Ideal for repairing electronic or electromechanical assemblies and for teaching. • DC / AC voltmeter: 0 to 600 V. • DC / AC ammeter: 0 to 10 A. • Ohmmeter: 0 to 40 MO. • Capacimeter: 0 to 100 μ F. • Frequency meter: 0 to 100 KHZ. • Cyclic ratio: 5% to 99 %.
- Diode test. • Continuity test with buzzer. • 600 V CAT III.

References :

	[G]
711A	803